

CETAC TECHNOLOGIES

SERVICE BULLETIN

Subject: Replacement of X-axis drive belt	Bulletin No: SB 1008
	Date Issued: 08/11/05
	Priority: Medium

Product: All Autosampler Product Lines
Serial Numbers: Between 040501ASX and 060501ASX
Serial Numbers start by month (MM), year (YY) and units built that month (i.e., MMYyxx)

Service Location: Customer Site CETAC Technologies

Responsibility: Customer Trained CETAC Representative

Replacement Parts: Customer CETAC Technologies

DESCRIPTION

Replacing the x-axis drive belt found to be faulty.

IMPLEMENTATION

Replace the x-axis drive belt using the instructions in the available documentation.

PARTS

Part Number	Description
450036	x-axis drive belt

AVAILABLE DOCUMENTATION